

Non-Compliance Notice - Issued

Permit Holder: Ovintiv Canada ULC
Discovery Date: 2026-09-01
As a result of Inspection 2026-3190

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0604-01 Issued Date: '2026-09-01' Status: Issued Outcome: Correction Duration: 24 Hours Correction Due Date: '2026-09-02'	Permit: 100108041 Well ID: 38936 Well Name: OVV HZ BRIARRIDGE 14-01-078-14 Location: DLS: 14-01-078-14 Legislation: Energy Resource Activities Act - 37 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (a) remedy the cause or source of the spillage; (b) contain and eliminate the spillage;
Non-Compliance Comment: H2S present in meter box for 14 - 1 - 78- 14 caused personal monitor to alarm. Inspection of meter box halted and message left for operator to address.	

Non-Compliance Number: 2026-0604-02 Issued Date: '2026-09-01' Status: Issued Outcome: Correction Duration: 30 Days	Permit: 100108041 Well ID: 38936 Well Name: OVV HZ BRIARRIDGE 14-01-078-14 Location: DLS: 14-01-078-14 Legislation: Drilling and Production Regulation - 15 15 (3) A well permit holder must ensure both of the following: (a) that the well site is maintained in a condition so as to minimize hazards, including but not limited to hazards associated with pits, holes, storage of materials and equipment; (b) that the well site is free of garbage, debris and derelict equipment.
---	--

Correction Due Date: '2026-10-01'	
Non-Compliance Comment: Pile of woody debris needs to be removed. Mating next to pile of debris needs to be assessed and removed if determined to be garbage as it appears to be. This mating is stacked on the opposite side of the lease from the other mating that appears to be still usable.	

Authorized by BCER