

## Non-Compliance Notice - Issued

Permit Holder: Saba Oil & Gas Ltd.  
Discovery Date: 2026-09-02  
As a result of Inspection 2026-3200

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

|                                                                                                                                                                                                                                                                                          |                                                                                                                                                                                                                                                                                                                                                                                                              |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Non-Compliance Number:</b><br><b>2026-0606-01</b><br><br><b>Issued Date:</b><br><b>'2026-09-03'</b><br><br><b>Status:</b><br><b>Issued</b><br><br><b>Outcome:</b><br><br><br><b>Correction Duration:</b><br><b>24 Hours</b><br><br><b>Correction Due Date:</b><br><b>'2026-09-04'</b> | <b>Permit:</b> 100001059<br><b>Well ID:</b> 00809<br><b>Well Name:</b> SABA O&G LAPRISE D- 091-H/094-G-08<br><b>Location:</b> NTS: D- 091-H/094-G-08<br><br><b>Legislation:</b><br>Energy Resource Activities Act<br>37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following:<br>(a) remedy the cause or source of the spillage; |
| <b>Non-Compliance Comment:</b> LEL gas was measured (Altair-5x) from well building PSV vent pipe: continuous venting (audible leak) was noted.                                                                                                                                           |                                                                                                                                                                                                                                                                                                                                                                                                              |

|                                                                                                                                                                                                                               |                                                                                                                                                                                                                                                                                                                                                                                                                                              |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Non-Compliance Number:</b><br><b>2026-0606-02</b><br><br><b>Issued Date:</b><br><b>'2026-09-03'</b><br><br><b>Status:</b><br><b>Issued</b><br><br><b>Outcome:</b><br><br><br><b>Correction Duration:</b><br><b>30 Days</b> | <b>Permit:</b> 100001059<br><b>Well ID:</b> 00809<br><b>Well Name:</b> SABA O&G LAPRISE D- 091-H/094-G-08<br><b>Location:</b> NTS: D- 091-H/094-G-08<br><br><b>Legislation:</b><br>Drilling and Production Regulation<br>25 (5) The well permit holder of an inactive well, within 60 days of the well becoming inactive, must do both of the following:<br>(a) suspend the well in a manner that ensures the ongoing integrity of the well; |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

|                                                                                                                                                                                                                                                                                                                           |  |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|
| Correction Due Date:<br><b>'2026-10-03'</b>                                                                                                                                                                                                                                                                               |  |
| <p>Non-Compliance Comment: Wellhead valve handles (master and wing valves) are not disabled (not chained/locked or removed). In addition, the flowline is not isolated from this wellhead (blinded/disconnected).</p> <p>KERMIT last reported gas production date: 2025-03 (&gt;16 months no reported gas production)</p> |  |

---

Authorized by BCER