

Non-Compliance Notice - Issued

Permit Holder: Canadian Natural Resources Limited
Discovery Date: 2026-09-22
As a result of Inspection 2026-3353

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Non-Compliance Number: 2026-0638-01 Issued Date: '2026-09-22' Status: Issued Outcome: Correction Duration: 30 Days Correction Due Date: '2026-10-22'	Permit: 100054950 Facility ID: 00022196 Facility Name: CNRL BEG A-035-B/094-G-01 001 Facility Type: Well Facility Location: NTS: A- 035-B/094-G-01 Legislation: Energy Resource Activities Act 37 (2) If spillage occurs, a permit holder or person carrying out an energy resource activity must promptly do all of the following: (b) contain and eliminate the spillage;
Non-Compliance Comment: H2S detected on personal monitor during meter run building entry test.	

Non-Compliance Number: 2026-0638-02 Issued Date: '2026-09-22' Status: Issued Outcome: Correction Duration: 30 Days Correction Due Date:	Permit: 100054950 Well ID: 21387 Well Name: CNRL BEG A- 035-B/094-G-01 Location: NTS: A- 035-B/094-G-01 Legislation: Drilling and Production Regulation - 15 15 (1) Until the well is abandoned, a well permit holder must ensure that a permanently legible and conspicuous sign is displayed and maintained at each well, and that sign must show all of the following: (a) the name of the well permit holder; (b) current emergency notification information, including a telephone number; (c) the location of the surface site of the well as specified in the well permit; (d) if the well may produce flammable gas, a flammable gas symbol
--	--

'2026-10-22'	from Schedule 1; (e) if the well may produce gas containing 100 ppm or greater of hydrogen sulphide, a poisonous gas symbol from Schedule 1;
Non-Compliance Comment: Signage obstructed by vegetation and warning symbols faded (See attached)	

Authorized by BCER