

## Inspection Report

Permit Holder: Pacific Canbriam Energy Limited  
Inspection: 2026-1396  
Inspection Date: 2026-04-30  
Inspection Outcome: Inspected

### Inspection Comment:

All wells were active at the time of inspection. All meters and meter runs are current in their service and calibrations.

#### Some observations;

The O-7-1 well cellar appears to have been excavated and while there is some flagging tape and planks beside it, it needs to be worked on to make it safer, especially if the issue has been resolved.

There is a sheen on the water in the cellars and hydrocarbon staining on the ground around a bunch of the well heads. I had a discussion with one of the field leads for Pacific Canbriam and we discussed the current state of the area around well heads and stains and there was going to be a plan to correct the current condition as well as going forward having cleaner cellars and reducing hydrocarbon staining when drilling is taking place. I mentioned I discussed the same issue with other companies and one technique was to cement the bottom of the cellar when drilling and keeping it clean.

While a well cellar is always considered a contaminated area there are measures that can be taken to reduce the amount of contamination and in the long term reduce remediation costs. The sheen and hydrocarbon staining are contained within close proximity to the well cellar and there is no concern for migration with the spring thaw. It is anticipated these cellars and stains will be cleaned up as per the much higher standard seen on other Pacific Canbriam well sites.

Overall, the well site needs a "spring clean up" and one field leads has already started in dealing with the many broken pieces of polyurethane foam. There is also some yellow jacket pipe that could be removed if no longer needed.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100107750  
Well ID: 38561  
Well Name: PACIFIC CANBRIAM HZ ALTARES 02-01-085-26  
Location: DLS: 02-01-085-26

Permit: 100107750  
Well ID: 38562  
Well Name: PACIFIC CANBRIAM HZ ALTARES A02-01-085-26  
Location: DLS: A02-01-085-26

Permit: 100107750  
Well ID: 38563  
Well Name: PACIFIC CANBRIAM HZ ALTARES B02-01-085-26  
Location: DLS: B02-01-085-26

Permit: 100107750  
Well ID: 38564  
Well Name: PACIFIC CANBRIAM HZ ALTARES C02-01-085-26  
Location: DLS: C02-01-085-26

Permit: 100107750  
Well ID: 38565  
Well Name: PACIFIC CANBRIAM HZ ALTARES D02-01-085-26  
Location: DLS: D02-01-085-26

Permit: 100107750  
Well ID: 38566  
Well Name: PACIFIC CANBRIAM HZ ALTARES E02-01-085-26  
Location: DLS: E02-01-085-26

Permit: 100115058  
Well ID: 43696  
Well Name: PACIFIC CANBRIAM HZ ALTARES F02-01-085-26  
Location: DLS: F02-01-085-26

Permit: 100115058  
Well ID: 43697  
Well Name: PACIFIC CANBRIAM HZ ALTARES G02-01-085-26  
Location: DLS: G02-01-085-26

Permit: 100115058  
Well ID: 43698  
Well Name: PACIFIC CANBRIAM HZ ALTARES 07-01-085-26  
Location: DLS: 07-01-085-26

Permit: 100115058  
Well ID: 43699  
Well Name: PACIFIC CANBRIAM HZ ALTARES A07-01-085-26  
Location: DLS: A07-01-085-26

Permit: 100115058  
Well ID: 43700  
Well Name: PACIFIC CANBRIAM HZ ALTARES B07-01-085-26  
Location: DLS: B07-01-085-26

Permit: 100115058  
Well ID: 43701  
Well Name: PACIFIC CANBRIAM HZ ALTARES C07-01-085-26  
Location: DLS: C07-01-085-26

Permit: 100115058  
Well ID: 43702  
Well Name: PACIFIC CANBRIAM HZ ALTARES D07-01-085-26  
Location: DLS: D07-01-085-26

Permit: 100115058  
Well ID: 43703  
Well Name: PACIFIC CANBRIAM HZ ALTARES E07-01-085-26  
Location: DLS: E07-01-085-26

Permit: 100115058  
Well ID: 43704  
Well Name: PACIFIC CANBRIAM HZ ALTARES F07-01-085-26  
Location: DLS: F07-01-085-26

Permit: 100115058  
Well ID: 43705  
Well Name: PACIFIC CANBRIAM HZ ALTARES G07-01-085-26  
Location: DLS: G07-01-085-26

Permit: 100115058  
Well ID: 43706  
Well Name: PACIFIC CANBRIAM HZ ALTARES H07-01-085-26  
Location: DLS: H07-01-085-26

Permit: 100115058  
Well ID: 43707  
Well Name: PACIFIC CANBRIAM HZ ALTARES I07-01-085-26  
Location: DLS: I07-01-085-26

Permit: 100115058  
Well ID: 43708  
Well Name: PACIFIC CANBRIAM HZ ALTARES J02-01-085-26  
Location: DLS: J02-01-085-26

Permit: 100115058  
Well ID: 43709  
Well Name: PACIFIC CANBRIAM HZ ALTARES K02-01-085-26  
Location: DLS: K02-01-085-26

Permit: 100115058  
Well ID: 43710  
Well Name: PACIFIC CANBRIAM HZ ALTARES L02-01-085-26  
Location: DLS: L02-01-085-26

Permit: 100117969  
Well ID: 49291  
Well Name: PACIFIC CANBRIAM HZ ALTARES M07-01-085-26  
Location: DLS: M07-01-085-26

Permit: 100117969  
Well ID: 49292  
Well Name: PACIFIC CANBRIAM HZ ALTARES N07-01-085-26  
Location: DLS: N07-01-085-26

Permit: 100117969  
Well ID: 49293  
Well Name: PACIFIC CANBRIAM HZ ALTARES O07-01-085-26  
Location: DLS: O07-01-085-26

Permit: 100117969  
Well ID: 49294  
Well Name: PACIFIC CANBRIAM HZ ALTARES P07-01-085-26  
Location: DLS: P07-01-085-26

Permit: 100117969  
Well ID: 49295  
Well Name: PACIFIC CANBRIAM HZ ALTARES Q07-01-085-26  
Location: DLS: Q07-01-085-26

Permit: 100117969  
Well ID: 49296  
Well Name: PACIFIC CANBRIAM HZ ALTARES R07-01-085-26  
Location: DLS: R07-01-085-26

Permit: 100117969  
Well ID: 49297  
Well Name: PACIFIC CANBRIAM HZ ALTARES S07-01-085-26  
Location: DLS: S07-01-085-26

Permit: 100117969  
Well ID: 49298  
Well Name: PACIFIC CANBRIAM HZ ALTARES L07-01-085-26  
Location: DLS: L07-01-085-26

Permit: 100115170  
Facility ID: 00027513  
Facility Name: PACIFIC CANBRIAM ALTARES 02-01-085-26 001  
Facility Type: Well Facility  
Location: DLS: 02-01-085-26

---

Authorized by BCER