

Inspection Report

Permit Holder: Whitecap Resources Inc.
Inspection: 2026-1781
Inspection Date: 2026-05-28
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

- Inactive electric pumpjack. No SCVF.
- wellhead valves chained and locked. Flowline is disconnected from the wellhead. Pumpjack disconnected. No polish rod in well.
- lease, access and signage are compliant.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100003294
Well ID: 02487
Well Name: WHITECAP ET AL BOUNDARY 10-23-085-14
Location: DLS: 10-23-085-14

Authorized by BCER