

## Inspection Report

Permit Holder: Whitecap Resources Inc.  
Inspection: 2026-1789  
Inspection Date: 2026-05-28  
Inspection Outcome: Inspected

### Inspection Comment:

#### COMMENTS:

- Inactive electric pumpjack. Wellhead valves chained and locked. Flowline is disconnected from the wellhead. Pumpjack disconnected and no polish rod in well.
- No SCVF-handle is missing on surface casing vent
- lease, access and signage are compliant.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100000812  
Well ID: 00643  
Well Name: WHITECAP ET AL BOUNDARY 14-23-085-14  
Location: DLS: 14-23-085-14

---

Authorized by BCER