

## Inspection Report

Permit Holder: Whitecap Resources Inc.  
Inspection: 2026-1794  
Inspection Date: 2026-05-28  
Inspection Outcome: Inspected

**Inspection Comment:****COMMENTS:**

- Inactive electric pumpjack. Pumpjack disconnected in place. No SCVF
- wellhead valves chained and locked. Flowline is disconnected from the wellhead.
- lease, access and signage are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 10000888  
Well ID: 00692  
Well Name: WHITECAP ET AL BOUNDARY 11-24-085-14  
Location: DLS: 11-24-085-14

---

Authorized by BCER