

## Inspection Report

Permit Holder: Whitecap Resources Inc.  
Inspection: 2026-1921  
Inspection Date: 2026-06-04  
Inspection Outcome: Inspected

### Inspection Comment:

#### COMMENTS:

-Inactive electric pumpjack disconnected in place. Wellhead valves chained and locked. Flowline is disconnected from the wellhead.

-No SCVF but handle is missing.

-lease, access and signage are compliant.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100002326  
Well ID: 01751  
Well Name: WHITECAP ET AL BOUNDARY 14-28-085-14  
Location: DLS: 14-28-085-14

---

Authorized by BCER