

## Inspection Report

Permit Holder: Whitecap Resources Inc.  
Inspection: 2026-1922  
Inspection Date: 2026-06-04  
Inspection Outcome: Inspected

### Inspection Comment:

#### COMMENTS:

- Inactive electric pumpjack disconnected in place. Wellhead valves chained and locked. Flowline is disconnected from the wellhead.
- No SCVF
- lease, access and signage are compliant.
- header building also on lease.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100002374  
Well ID: 01786  
Well Name: WHITECAP ET AL BOUNDARY 06-28-085-14  
Location: DLS: 06-28-085-14

---

Authorized by BCER