

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-3152
Inspection Date: 2026-08-26
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1312HRS.

Access road- Limited vegetation growing on access road. No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. No barricades in place (Limited risk due to isolated location). Signage in place. Signage fading (See attached). Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test.

Building entry test- No alarms on personal monitor. Building out of service.

Tanks and secondary containment on site- secondary containment nearly full (See attached). 1/4 turn discharge valve on secondary containment missing plug (See attached).

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100031067
Well ID: 14250
Well Name: TOURMALINE NIG C- 001-G/094-H-04
Location: NTS: C- 001-G/094-H-04

Authorized by BCER



Inspection Number: 2026-3152
Inspection Date: 2026-08-26

Letter ID: L2604463
Letter Date: 2026-08-28