

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-3258
Inspection Date: 2026-09-01
Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1527HRS.

Access road- Road obstructed by water line (Seer attached). No concerns at the time of inspection.

Lease environment-Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. Barricades in place. Signage in place. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor. Building out of service.

Tanks and secondary containment on site- Needle valve missing plug on outlet, tank appears empty (low risk). No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100003715
Well ID: 02784
Well Name: TOURMALINE NIG B- 068-B/094-H-04
Location: NTS: B- 068-B/094-H-04

Authorized by BCER