

## Non-Compliance Notice - Issued

Permit Holder: Canadian Natural Resources Limited  
Discovery Date: 2026-06-16  
As a result of Inspection 2026-2066

**Notice Comment:**

Storage: (1) The earthen berm containment is not of sufficient capacity to contain a spill from the tanker used on site; and (2) the southern earthen boundary of the containment has eroded and is no longer effective.

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: <b>2026-0398-01</b></p> <p>Issued Date: <b>'2026-06-22'</b></p> <p>Status: <b>Issued</b></p> <p>Outcome:</p> <p>Correction Duration: <b>14 Days</b></p> <p>Correction Due Date: <b>'2026-07-06'</b></p>	<p>Permit: 100021649 Well ID: 11079 Well Name: CNRL ET AL HZ HELMET A- 054-B/094-P-15 Location: NTS: A- 054-B/094-P-15</p> <p>Legislation: Energy Resource Activities Act 37 (1) A permit holder and a person carrying out an energy resource activity must (a) prevent spillage, and</p>
<p>Non-Compliance Comment: Storage: (1) The earthen berm containment is not of sufficient capacity to contain a spill from the tanker used on site; and (2) the southern earthen boundary of the containment has eroded and is no longer effective.</p>	

---

Authorized by BCER