

Non-Compliance Notice - Issued

Permit Holder: Canadian Natural Resources Limited
Discovery Date: 2026-07-07
As a result of Inspection 2026-2287

An Inspection was conducted and as a result the following Non-Compliances were found. These Non-Compliances must be corrected by the required Correction Due Dates as indicated below. Consideration should be given to checking your other locations for similar Non-Compliances. To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

<p>Non-Compliance Number: 2026-0452-01</p> <p>Issued Date: '2026-07-09'</p> <p>Status: Issued</p> <p>Outcome:</p> <p>Correction Duration: 30 Days</p> <p>Correction Due Date: '2026-08-08'</p>	<p>Permit: 100027703 Well ID: 13179 Well Name: CNRL HZ W BUICK A-A067-E/094-A-14 Location: NTS: A-A067-E/094-A-14</p> <p>Legislation: Drilling and Production Regulation - 25 25 (5) The well permit holder of an inactive well, within 60 days of the well becoming inactive, must do both of the following: (a) suspend the well in a manner that ensures the ongoing integrity of the well; (b) ensure positive isolation between the well and the flowline by disconnecting the well from the flowline or by other means.</p>
<p>Non-Compliance Comment: Valve handles not chained locked & secure or handles removed (see attached).</p> <p>No positive isolation between well & flowline (see attached).</p>	

Authorized by BCER