

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-1377
Inspection Date: 2026-05-01
Inspection Outcome: Inspected

Inspection Comment:

Access signage clear and legible.

Matting being stored on lease and internal parts of line heaters being stored on site. Sign of livestock being on site and near wellheads/buildings.

Inspect wells 0-A. No SCV flow observed. Barricades present. Signage clear. Critical valves locked. Meters inspected.

0 well has a clamshell damaged on needle valve leading to a pressure sensor off annulus valve. Spoke with Tourmaline Production compliance operator. Who had clamshell replaced same day. See attached photo.

Pig barrel - inspected.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100077794
Well ID: 28942
Well Name: TOURMALINE HZ SUNDOWN D- 043-H/093-P-10
Location: NTS: D- 043-H/093-P-10

Permit: 100079977
Well ID: 30167
Well Name: TOURMALINE HZ SUNDOWN D-A043-H/093-P-10
Location: NTS: D-A043-H/093-P-10

Permit: 100077794
Facility ID: 00025845
Facility Name: TOURMALINE HERITAGE D-043-H/093-P-10 001
Facility Type: Well Facility
Location: NTS: D- 043-H/093-P-10



Permit: 100079977
Facility ID: 00026068
Facility Name: TOURMALINE HERITAGE D-043-H/093-P-10 002
Facility Type: Well Facility
Location: NTS: D- 043-H/093-P-10

Authorized by BCER