

Inspection Report

Permit Holder: Whitecap Resources Inc.
Inspection: 2026-1389
Inspection Date: 2026-04-30
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

16-18-84-13:

- active small electric pumpjack. No SCVF
- small stain on ground and wellhead, soaker pads are in place.
- pipeline signage reads "A16-18". Why? As there is no well A16-18-84-13.

B16-18-84-13:

- pumpjack inactive at time of inspection with active ESD. No SCVF
- header building has signage referring to A16-18?

lease, access and well signage are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100009309
Well ID: 06346
Well Name: WHITECAP ET AL BOUNDARY 16-18-084-13
Location: DLS: 16-18-084-13

Permit: 100082407
Well ID: 31399
Well Name: WHITECAP HZ BOUNDARY B16-18-084-13
Location: DLS: B16-18-084-13

Permit: 100009309
Facility ID: 00018915
Facility Name: WHITECAP BOUNDARYLAKE 16-18-084-13 001
Facility Type: Well Facility
Location: DLS: 16-18-084-13

Permit: 100082407
Facility ID: 00026192
Facility Name: WHITECAP BOUNDARYLAKE 16-18-084-13 002
Facility Type: Well Facility
Location: DLS: 16-18-084-13

Authorized by BCER