

Inspection Report

Permit Holder: Whitecap Resources Inc.
Inspection: 2026-1391
Inspection Date: 2026-04-30
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

12-20-84-13:

-active pumpjack, No SCVF

B12-20-84-13:

-active electric pumpjack with AV/SD. No SCVF

lease, access and signage are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100009367
Well ID: 06387
Well Name: WHITECAP ET AL BOUNDARY 12-20-084-13
Location: DLS: 12-20-084-13

Permit: 100081087
Well ID: 30634
Well Name: WHITECAP ET AL HZ BOUNDARY B12-20-084-13
Location: DLS: B12-20-084-13

Permit: 100009367
Facility ID: 00018921
Facility Name: WHITECAP BOUNDARYLAKE 12-20-084-13 001
Facility Type: Well Facility
Location: DLS: 12-20-084-13



Permit: 100081087
Facility ID: 00026124
Facility Name: WHITECAP BOUNDARYLAKE 12-20-084-13 002
Facility Type: Well Facility
Location: DLS: 12-20-084-13

Authorized by BCER