

## Inspection Report

Permit Holder: Canadian Natural Resources Limited  
Inspection: 2026-1409  
Inspection Date: 2026-05-05  
Inspection Outcome: Inspected

### Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1110HRS.

Access road- Very wet & muddy, unable to access with truck. Walk in

Lease Equipment: Wellhead Suspended. Wellhead is surrounded by a metal platform (see attached). Signage on wellhead, Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100069869  
Well ID: 25805  
Well Name: CNRL MARTIN C- 087-F/094-H-06  
Location: NTS: C- 087-F/094-H-06

Permit: 100069869  
Facility ID: 00024347  
Facility Name: CNRL MARTIN C-087-F/094-H-06 001  
Facility Type: Well Facility  
Location: NTS: C- 087-F/094-H-06

---

Authorized by BCER