

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-1410
Inspection Date: 2026-05-05
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1137HRS.

Access road- Wet & muddy, unable to access with truck.

Lease Equipment: Wellhead appears open. Records indicate flow as of March 2026. No barricades in place (limited risk due to isolated location of wellhead). Signage on building, flammable decal faded and illegible. Insulated blanket decaying and starting to lose insulation (See attached). Surface casing vent flow test- No Flow detected from glove test.

Building entry test- No alarms on personal monitor. Building out of service.

Note, flowline diverts from building to underground line. Closed spec blind on flowline to flare.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100011542
Well ID: 07231
Well Name: CNRL MARTIN B- 090-F/094-H-06
Location: NTS: B- 090-F/094-H-06

Authorized by BCER