

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-1411
Inspection Date: 2026-05-05
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1223HRS.

Access road- Very wet & muddy, unable to access with truck.

Lease Equipment: Wellhead Suspended (well last produced March 2024). No barricades in place (Limited risk due to isolated location). Signage on building, No positive isolation. Valve handles not chained, locked and secure. Insulated blanket decaying and starting to lose insulation (See attached). Surface casing vent flow test- No Flow detected from glove test.

Building entry test- No alarms on personal monitor.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100016657
Well ID: 09074
Well Name: CNRL MARTIN C- 033-E/094-H-06
Location: NTS: C- 033-E/094-H-06

Authorized by BCER