

Inspection Report

Permit Holder: Cenovus Energy Inc.
Inspection: 2026-1412
Inspection Date: 2026-05-05
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Road washed out.

See attached pictures and non-compliance for more details.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100065626
Road Number: 00594
Segment IDs (Location): 001 (From DLS: 05-29-077-20 To DLS: 15-25-077-20)

Authorized by BCER