

Inspection Report

Permit Holder: Cenovus Energy Inc.
Inspection: 2026-1413
Inspection Date: 2026-05-06
Inspection Outcome: Inspected

Inspection Comment:

Access road showing some signs of erosion near lease entrance.

Pad clean.

Inspected well. Signage clear and legible. No SCV flow observed. Meter building inspected.

Pig barrel inspected.

Chemical tanks and secondary containments inspected. Note that one secondary containment has some side wall damage and may not hold the tank contents if the tank were full. See attached photos.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100011660
Well ID: 07301
Well Name: CVE ENERGY JACKPINE A- 089-B/093-P-07
Location: NTS: A- 089-B/093-P-07

Authorized by BCER