

## Inspection Report

Permit Holder: Cenovus Energy Inc.  
Inspection: 2026-1414  
Inspection Date: 2026-05-05  
Inspection Outcome: Inspected

### Inspection Comment:

Access road showing some signs of erosion near lease entrance.

Bridge at 55.31628\*N, 120.74132\*W has delineator fallen and not clearly posted, and some signs of abutment washing.

\*\*Please provide both visual and technical inspection records of this bridge for the last 6years. Requesting this information be sent to the inspector within 5 business days.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100079911  
Road Number: 00291  
Segment IDs (Location): 001 (From NTS: A- 076-C/093-P-07 To NTS: A- 089-B/093-P-07)

---

Authorized by BCER