

Inspection Report

Permit Holder: Whitecap Resources Inc.
Inspection: 2026-1431
Inspection Date: 2026-05-06
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-I walked in past the matting in the road due to muddy conditions.

5-31-84-13:

-wellhead only. Valves chained and locked and flowline is disconnected from the wellhead. Guarding around wellhead.

A5-31-84-13:

-wellhead valves chained and locked and flowline is disconnected from the wellhead. No SCVF. Guarding around wellhead. No equipment.

lease, access and signage are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100003631
Well ID: 02733
Well Name: WHITECAP ET AL BOUNDARY 05-31-084-13
Location: DLS: 05-31-084-13

Permit: 100015130
Well ID: 08478
Well Name: WHITECAP ET AL HZ BOUNDARY A05-31-084-13
Location: DLS: A05-31-084-13

Permit: 100016367
Facility ID: 00001686
Facility Name: WHITECAP BOUNDARYLAKE 05-31-084-13 001
Facility Type: Injection Station
Location: DLS: 05-31-084-13



Inspection Number: 2026-1431
Inspection Date: 2026-05-06

Letter ID: L2602065
Letter Date: 2026-05-08

Authorized by BCER