

## Inspection Report

Permit Holder: Shell Canada Limited  
Inspection: 2026-1438  
Inspection Date: 2026-05-05  
Inspection Outcome: Inspected

### Inspection Comment:

Access signage clear and legible. Access inspected.

Wellhead inspected. Signage clear and legible. Wellhead fenced. Meter inspected.  
Critical valves locked. No SCV flow observed.

Chemical tanks inspected.

Associated pipeline well vegetated.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100053761  
Well ID: 21144  
Well Name: SHELL BRASSEY 11-21-077-19  
Location: DLS: 11-21-077-19

Permit: 100053761  
Facility ID: 00022086  
Facility Name: SHELL BRASSEY 11-21-077-19 001  
Facility Type: Well Facility  
Location: DLS: 11-21-077-19

Permit: 100081385  
Road Number: 03106  
Segment IDs (Location): 001 (From DLS: 03-26-077-19 To DLS: 11-21-077-19)

---

Authorized by BCER