

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-1442
Inspection Date: 2026-05-07
Inspection Outcome: Inspected

Inspection Comment:

- * Travel to OVV HZ SUNRISE 16-27-079-16, sign in orientation.
- * Meet and greet site supervisors. discuss operations and review documentation.
- * Conduct walk around and visual inspection.
- * sound monitoring in place, sound panel planned to arrive later
- * Operations going through final stages prior to start up.
- * Discuss visual inspection with supervisor.
- * Sign out return to Dawson Creek
- * No concerns upon submitting this report.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100111508
Well ID: 41522
Well Name: OVV HZ SUNRISE K16-27-079-16
Location: DLS: K16-27-079-16

Authorized by BCER