

Inspection Report

Permit Holder: Bonterra Energy Corp.
Inspection: 2026-1457
Inspection Date: 2026-05-07
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1124HRS.

Access road- No concerns at the time of inspection.

Lease Equipment: ESD appears open. No barricades in place (Limited risk due to isolated location). Signage at access road faded, signage at lease entrance missing flammable symbol. Wellhead and flowline covered in insulated wrap.
Surface casing vent flow test- No Flow detected from glove test.

Building entry test- No alarms on personal monitor.

Chemical tank and secondary containment on site- No concerns at time of inspection.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100052539
Well ID: 20970
Well Name: BONTERRA ET AL UMBACH D- 031-E/094-H-03
Location: NTS: D- 031-E/094-H-03

Permit: 100052539
Facility ID: 00022000
Facility Name: BONTERRA UMBACH D-031-E/094-H-03 001
Facility Type: Well Facility
Location: NTS: D- 031-E/094-H-03



Inspection Number: 2026-1457
Inspection Date: 2026-05-07

Letter ID: L2602095
Letter Date: 2026-05-08

Authorized by BCER