

Inspection Report

Permit Holder: Cenovus Energy Inc.
Inspection: 2026-1461
Inspection Date: 2026-05-06
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Access inspected. Access sign clear and legible.

Pad clean.

Wellhead inspected. Signage clear and legible. No SCV flow observed. Meter building inspected.

Chemical tanks inspected. See non-compliance.

Chemical pump has drip tray that appears to be 50% full of liquid. See pictures.

Associated pipeline well vegetated.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100009728
Well ID: 06590
Well Name: CVE ENERGY JACKPINE A- 089-C/093-P-07
Location: NTS: A- 089-C/093-P-07

Permit: 100083360
Road Number: 03733
Segment IDs (Location): 002 (From NTS: A- 089-C/093-P-07 To NTS: B- 098-C/093-P-07)

Authorized by BCER