

## Inspection Report

Permit Holder: Shell Canada Limited  
Inspection: 2026-1463  
Inspection Date: 2026-05-06  
Inspection Outcome: Inspected

### Inspection Comment:

9-33-80-18

Signage no concerns.

SCV no venting observed.

Wellhead chained and locked.

Shutdown isolation valve locked open.

Bettis actuator no concerns.

Metering cabinet no concerns.

Chemical injection system no concerns.

Chemical tank with secondary containment no concerns.

No concerns identified at time of inspection.

A9-33-80-18

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked open.

Bettis actuator no concerns.

Metering cabinet no concerns.

Chemical injection system no concerns.

Chemical tank with secondary containment no concerns.

No concerns identified at time of inspection.

B9-33-80-18

Signage no concerns.

SCV no venting observed.

Wellhead chained and locked.

Shutdown isolation valve locked open.

Bettis actuator no concerns.

Metering cabinet no concerns.

Chemical injection system no concerns.

Chemical tank with secondary containment no concerns.

No concerns identified at time of inspection.

C9-33-80-18

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked open.

Bettis actuator no concerns.

Metering cabinet no concerns.

Chemical injection system no concerns.

Chemical tank with secondary containment no concerns.

No concerns identified at time of inspection.

D9-33-80-18

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked open.

Bettis actuator no concerns.

Metering cabinet no concerns.

Chemical injection system no concerns.

Chemical tank with secondary containment no concerns.

No concerns identified at time of inspection.

E9-33-80-18

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked open.

Bettis actuator no concerns.

Metering cabinet no concerns.

Chemical injection system no concerns.

Chemical tank with secondary containment no concerns.

No concerns identified at time of inspection.

TEG no concerns.

Separator building with secondary containment no concerns.

Pigging area no concerns.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100070051

Well ID: 25888

Well Name: SHELL HZ SUNSET 09-33-080-18

Location: DLS: 09-33-080-18

Permit: 100070052  
Well ID: 25889  
Well Name: SHELL HZ SUNSET A09-33-080-18  
Location: DLS: A09-33-080-18

Permit: 100070053  
Well ID: 25890  
Well Name: SHELL HZ SUNSET B09-33-080-18  
Location: DLS: B09-33-080-18

Permit: 100070054  
Well ID: 25891  
Well Name: SHELL HZ SUNSET C09-33-080-18  
Location: DLS: C09-33-080-18

Permit: 100070055  
Well ID: 25892  
Well Name: SHELL HZ SUNSET D09-33-080-18  
Location: DLS: D09-33-080-18

Permit: 100070056  
Well ID: 25893  
Well Name: SHELL HZ SUNSET E09-33-080-18  
Location: DLS: E09-33-080-18

Permit: 100070051  
Facility ID: 00024384  
Facility Name: SHELL HERITAGE 09-33-080-18 001  
Facility Type: Well Facility  
Location: DLS: 09-33-080-18

Permit: 100070052  
Facility ID: 00024385  
Facility Name: SHELL HERITAGE 09-33-080-18 002  
Facility Type: Well Facility  
Location: DLS: 09-33-080-18

Permit: 100070053  
Facility ID: 00024386  
Facility Name: SHELL HERITAGE 09-33-080-18 003  
Facility Type: Well Facility  
Location: DLS: 09-33-080-18

Permit: 100070054  
Facility ID: 00024387  
Facility Name: SHELL HERITAGE 09-33-080-18 004  
Facility Type: Well Facility  
Location: DLS: 09-33-080-18

Permit: 100070055  
Facility ID: 00024388  
Facility Name: SHELL HERITAGE 09-33-080-18 005  
Facility Type: Well Facility  
Location: DLS: 09-33-080-18

Permit: 100070056  
Facility ID: 00024389  
Facility Name: SHELL HERITAGE 09-33-080-18 006  
Facility Type: Well Facility  
Location: DLS: 09-33-080-18

---

Authorized by BCER