

## Inspection Report

Permit Holder: Tourmaline Oil Corp.  
Inspection: 2026-1468  
Inspection Date: 2026-05-07  
Inspection Outcome: Inspected

### Inspection Comment:

Access and access sign inspected. Access has some signs of erosion. Large tree across the road approx. 450m from the lease.

Pad clean.

Inspect wells. Wellheads barricaded. Signage clear and legible. No SCV flow observed. Critical valves locked out. 0 well has audible hiss on fitting off wing valve. See attached picture. Notified ops, who attended same day and corrected leak by tightening fitting.

Pig barrels inspected.

Line heater internal parts stored on site.

Associated pipeline well vegetated.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100061457  
Well ID: 23269  
Well Name: TOURMALINE SUNDOWN D- 085-A/093-P-10  
Location: NTS: D- 085-A/093-P-10

Permit: 100065158  
Well ID: 24255  
Well Name: TOURMALINE HZ SUNDOWN D-A085-A/093-P-10  
Location: NTS: D-A085-A/093-P-10

Permit: 100061457  
Facility ID: 00023033  
Facility Name: TOURMALINE SUNDOWN D-085-A/093-P-10 001  
Facility Type: Well Facility  
Location: NTS: D- 085-A/093-P-10



Permit: 100065158  
Facility ID: 00023581  
Facility Name: TOURMALINE HERITAGE D-085-A/093-P-10 003  
Facility Type: Well Facility  
Location: NTS: D- 085-A/093-P-10

---

Authorized by BCER