

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-1471
Inspection Date: 2026-05-07
Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1230HRS.

Access road- Water accumulation at entrance. No concerns at the time of inspection.

Lease Equipment: A-A4-E Well: ESD appears open. No barricades in place (Limited risk due to isolated location). Signage in place. Wellhead covered in insulated wrap. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor.

A-4-E Well: ESD appears open. No barricades in place (Limited risk due to isolated location). Signage in place. Wellhead covered in insulated wrap. Surface casing vent flow test- Unable to perform due to mud and water around wellhead (See attached). Building entry test- No alarms on personal monitor.

Chemical tanks and pumps on site- No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100074232
Well ID: 27512
Well Name: CNRL ET AL HZ UMBACH A- 004-E/094-H-03
Location: NTS: A- 004-E/094-H-03

Permit: 100074568
Well ID: 27750
Well Name: CNRL ET AL HZ UMBACH A-A004-E/094-H-03
Location: NTS: A-A004-E/094-H-03

Permit: 100074232
Facility ID: 00025241
Facility Name: CNRL NORTHERNMONTNEY A-004-E/094-H-03 001
Facility Type: Well Facility
Location: NTS: A- 004-E/094-H-03

Permit: 100074568
Facility ID: 00025355
Facility Name: CNRL NORTHERNMONTNEY A-004-E/094-H-03 002
Facility Type: Well Facility
Location: NTS: A- 004-E/094-H-03

Authorized by BCER