

Inspection Report

Permit Holder: NTE Energy Canada Ltd.
Inspection: 2026-1472
Inspection Date: 2026-05-07
Inspection Outcome: Inspected

Inspection Comment:

OGC File #: 9632796

Road #: 00319

Road Name: Elleh

The 1st and 2nd bridge from the SYD/61 Road junction are missing each a corner marker: right (1) and left(1) handed placard (W-54 R type sign).

A follow-up inspection will be completed in about 30 days.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100049476

Road Number: 00319

Segment IDs (Location): 001 (From NTS: A- 037-A/094-J-09 To NTS: A- 021-A/094-J-09)

Authorized by BCER