

## Inspection Report

Permit Holder: Canadian Natural Resources Limited  
Inspection: 2026-1473  
Inspection Date: 2026-05-07  
Inspection Outcome: Inspected

### Inspection Comment:

Field triggered inspection of surface equipment on site.

Performed inspection of location at 1255HRS.

Access road- Vegetation growing on access road. Officer had to walk in due to wet conditions.

Lease Equipment: Wellhead Suspended. No barricades in place (Limited risk due to isolated location). Signage in place, Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100066540  
Well ID: 24706  
Well Name: CNRL UMBACH C- 100-C/094-H-03  
Location: NTS: C- 100-C/094-H-03

---

Authorized by BCER