

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-1475
Inspection Date: 2026-05-07
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1407HRS.

Access road- Road has rutted tire tracks in areas. No concerns at the time of inspection.

Lease Equipment: Wellhead ESD appears open. Barricades in place. Signage in place. Wellhead covered in insulated wrap. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor.

Chemical tank and pump on site- No concerns at time of inspection

Pig Station- Pipe insulation falling off flowline and laying on ground. No other concerns at time of inspection.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100074276
Well ID: 27528
Well Name: CNRL ET AL HZ UMBACH D- 052-D/094-H-03
Location: NTS: D- 052-D/094-H-03

Permit: 100074276
Facility ID: 00025242
Facility Name: CNRL NORTHERNMONTNEY D-052-D/094-H-03 001
Facility Type: Well Facility
Location: NTS: D- 052-D/094-H-03



Inspection Number: 2026-1475
Inspection Date: 2026-05-07

Letter ID: L2602115
Letter Date: 2026-05-08

Authorized by BCER