

## Inspection Report

Permit Holder: Canadian Natural Resources Limited  
Inspection: 2026-1476  
Inspection Date: 2026-05-07  
Inspection Outcome: Inspected

### Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1445HRS.

Access road- No concerns at the time of inspection.

NOTE: Accumulation of scrap pallets and discarded wood products south end of location (See attached).

Lease Equipment: D-36-D Wellhead: ESD appears open. Barricades in place. Signage in place. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor.

D-A36-D Wellhead: ESD appears open. Barricades in place. Signage in place. Surface casing vent flow test- No Flow detected from glove test. Building entry test- No alarms on personal monitor.

Test Separator Building entry test- No alarms on personal monitor. No concerns at time of inspection.

Chemical tanks and pumps on site- No concerns at time of inspection.

Pig Station- No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100079139  
Well ID: 29712  
Well Name: CNRL HZ NIG D- 036-D/094-H-03  
Location: NTS: D- 036-D/094-H-03

Permit: 100079191  
Well ID: 29714  
Well Name: CNRL HZ NIG D-B036-D/094-H-03  
Location: NTS: D-B036-D/094-H-03



Inspection Number: 2026-1476  
Inspection Date: 2026-05-07

Letter ID: L2602117  
Letter Date: 2026-05-08

---

Authorized by BCER