

Inspection Report

Permit Holder: Whitecap Resources Inc.
Inspection: 2026-1477
Inspection Date: 2026-05-06
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

- active electric pumpjack with AV/SD. No SCVF. Guarding around all equipment.
- quite a bit of oil mixed in with the water, inside of the chemical tank containment. Being dumped in there from the scrubber drain bucket?
- lease, access and signage are compliant.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100082680
Well ID: 31476
Well Name: WHITECAP HZ BOUNDARY 03-32-084-13
Location: DLS: 03-32-084-13

Permit: 100082680
Facility ID: 00026198
Facility Name: WHITECAP BOUNDARYLAKE 03-32-084-13 001
Facility Type: Well Facility
Location: DLS: 03-32-084-13

Authorized by BCER