

Inspection Report

Permit Holder: Whitecap Resources Inc.
Inspection: 2026-1494
Inspection Date: 2026-05-07
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

- active electric pumpjack.
- No SCVF-the handle is either missing or buried in dirt/gravel.
- Separator and tank across from the well.
- Guarding around all equipment
- lease, access and signage are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100001316
Well ID: 01023
Well Name: WHITECAP ET AL BOUNDARY 08-10-084-14
Location: DLS: 08-10-084-14

Permit: 100010764
Facility ID: 00000348
Facility Name: WHITECAP BOUNDARYLAKE 08-10-084-14 001
Facility Type: Satellite Battery
Location: DLS: 08-10-084-14

Authorized by BCER