

Inspection Report

Permit Holder: Whitecap Resources Inc.
Inspection: 2026-1500
Inspection Date: 2026-05-07
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

- H2O injection with cover. No SCVF. Guarding around the equipment.
- There is a hole in the ground at the entrance of the building. This could be a hazard for personnel.
- lease, access and signage are compliant.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100001403
Well ID: 01079
Well Name: WHITECAP ET AL BOUNDARY 16-10-084-14
Location: DLS: 16-10-084-14

Authorized by BCER