

Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-1501
Inspection Date: 2026-05-07
Inspection Outcome: Inspected

Inspection Comment:**COMMENTS:**

- active gas well. No SCVF
- building and flarestack onsite.
- lease, access and signage are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100015751
Well ID: 08710
Well Name: CANLIN ET AL BOUNDARY 03-15-084-14
Location: DLS: 03-15-084-14

Authorized by BCER