

## Inspection Report

Permit Holder: Tourmaline Oil Corp.  
Inspection: 2026-1509  
Inspection Date: 2026-05-08  
Inspection Outcome: Inspected

### Inspection Comment:

Site 16-07-080-17 was inspected at or about 1200 hours, it was 15 & sunny. The following was included in the inspection:  
Access and signage: no concerns  
Site: dry, clean  
Wellheads: Bull plugs, SCV, locks, leaks, -D well glove and bubble tested, all SCV glove tested, C well requires and update in IRIS.  
Meter/separator buildings: locks, leaks, caps, vents, - E separator building has salt build up on tubing joint see photos

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100061497  
Well ID: 23318  
Well Name: TOURMALINE ET AL SUNRISE 16-07-080-17  
Location: DLS: 16-07-080-17

Permit: 100076810  
Well ID: 28690  
Well Name: TOURMALINE HZ SUNRISE B16-07-080-17  
Location: DLS: B16-07-080-17

Permit: 100076811  
Well ID: 28691  
Well Name: TOURMALINE HZ SUNRISE C16-07-080-17  
Location: DLS: C16-07-080-17

Permit: 100076812  
Well ID: 28692  
Well Name: TOURMALINE HZ SUNRISE D16-07-080-17  
Location: DLS: D16-07-080-17

Permit: 100079966  
Well ID: 30103  
Well Name: TOURMALINE HZ SUNRISE E16-07-080-17  
Location: DLS: E16-07-080-17

Permit: 100079967  
Well ID: 30104  
Well Name: TOURMALINE HZ SUNRISE F16-07-080-17  
Location: DLS: F16-07-080-17

Permit: 100079968  
Well ID: 30105  
Well Name: TOURMALINE HZ SUNRISE G16-07-080-17  
Location: DLS: G16-07-080-17

Permit Holder: Tourmaline Oil Corp.

---

Authorized by BCER