

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-1526
Inspection Date: 2026-05-08
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Site 04-23-080-17 was inspected at or about 0920 hours, it was 11 & sunny. The following was included in the inspection:

Access and signage: no concerns

Site: rutted, dry, small pile of rig mats stored at the entrance.

Wellheads: Bull plugs, SCV, locks, leaks, - A04-23 has positive isolation - handles will need to be chained/ locked, Chokes on M, G drips and staining

Meter/separator buildings: locks, leaks, caps, vents, - no concerns

Chemical tanks: leaks, grounds, caps, - no concerns

Operator was made aware issues - via message a list of issues to attend to/ the operator attended to the site fixed and clean up and put in a work order.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100082057
Well ID: 31208
Well Name: OVV CRP HZ SUNRISE 04-23-080-17
Location: DLS: 04-23-080-17

Permit: 100082058
Well ID: 31209
Well Name: OVV CRP HZ SUNRISE A04-23-080-17
Location: DLS: A04-23-080-17

Permit: 100082059
Well ID: 31210
Well Name: OVV CRP HZ SUNRISE B04-23-080-17
Location: DLS: B04-23-080-17

Permit: 100082060
Well ID: 31211
Well Name: OVV CRP HZ SUNRISE C04-23-080-17
Location: DLS: C04-23-080-17

Permit: 100082061
Well ID: 31212
Well Name: OVV CRP HZ SUNRISE D04-23-080-17
Location: DLS: D04-23-080-17

Permit: 100082062
Well ID: 31213
Well Name: OVV CRP HZ SUNRISE E04-23-080-17
Location: DLS: E04-23-080-17

Permit: 100082063
Well ID: 31214
Well Name: OVV CRP HZ SUNRISE F04-23-080-17
Location: DLS: F04-23-080-17

Permit: 100082064
Well ID: 31215
Well Name: OVV CRP HZ SUNRISE G04-23-080-17
Location: DLS: G04-23-080-17

Permit: 100104673
Well ID: 37220
Well Name: OVV HZ SUNRISE O04-23-080-17
Location: DLS: O04-23-080-17

Permit: 100104673
Well ID: 37230
Well Name: OVV HZ SUNRISE I04-23-080-17
Location: DLS: I04-23-080-17

Permit: 100104673
Well ID: 37231
Well Name: OVV HZ SUNRISE J04-23-080-17
Location: DLS: J04-23-080-17

Permit: 100104673
Well ID: 37232
Well Name: OVV HZ SUNRISE K04-23-080-17
Location: DLS: K04-23-080-17

Permit: 100104673
Well ID: 37233
Well Name: OVV HZ SUNRISE L04-23-080-17
Location: DLS: L04-23-080-17

Permit: 100104673
Well ID: 37234
Well Name: OVV HZ SUNRISE M04-23-080-17
Location: DLS: M04-23-080-17

Permit: 100104673
Well ID: 37235
Well Name: OVV HZ SUNRISE N04-23-080-17
Location: DLS: N04-23-080-17

Permit: 100105680
Facility ID: 00026739
Facility Name: OVV SUNRISE 04-23-080-17 001
Facility Type: Well Facility
Location: DLS: 04-23-080-17

Permit Holder: Ovintiv Canada ULC

Authorized by BCER