

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-1527
Inspection Date: 2026-05-08
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Site 04-14-080-17 was inspected at or about 1020 hours, it was 16 & sunny. The operator was called to the site and was made aware with joint walked through of various issues. The following was included in the inspection:

Access and signage: no concerns

Site: rutted, dry, various small bits of garbage (cut zip ties, tags - paper, metal)

Wellheads: Bull plugs, SCV, locks, leaks, -drips and stains from various chokes

Meter/separator buildings: locks, leaks, caps, vents, - K orifice plate changer salt build up

Chemical tanks: leaks, grounds, caps, - one near the pig station leaking, operation fixed while on site

Riser & pig stations: chains, grounds, - no concerns

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100080841
Well ID: 30481
Well Name: OVV HZ SUNRISE 04-14-080-17
Location: DLS: 04-14-080-17

Permit: 100080842
Well ID: 30505
Well Name: OVV HZ SUNRISE A04-14-080-17
Location: DLS: A04-14-080-17

Permit: 100080843
Well ID: 30506
Well Name: OVV HZ SUNRISE B04-14-080-17
Location: DLS: B04-14-080-17

Permit: 100080844
Well ID: 30507
Well Name: OVV HZ SUNRISE C04-14-080-17
Location: DLS: C04-14-080-17

Permit: 100080845
Well ID: 30508
Well Name: OVV HZ SUNRISE D04-14-080-17
Location: DLS: D04-14-080-17

Permit: 100080846
Well ID: 30509
Well Name: OVV HZ SUNRISE E04-14-080-17
Location: DLS: E04-14-080-17

Permit: 100080847
Well ID: 30510
Well Name: OVV HZ SUNRISE F04-14-080-17
Location: DLS: F04-14-080-17

Permit: 100080848
Well ID: 30511
Well Name: OVV HZ SUNRISE G04-14-080-17
Location: DLS: G04-14-080-17

Permit: 100105158
Well ID: 36265
Well Name: OVV HZ SUNRISE H04-14-080-17
Location: DLS: H04-14-080-17

Permit: 100105158
Well ID: 36266
Well Name: OVV HZ SUNRISE I04-14-080-17
Location: DLS: I04-14-080-17

Permit: 100105158
Well ID: 36267
Well Name: OVV HZ SUNRISE J04-14-080-17
Location: DLS: J04-14-080-17

Permit: 100105158
Well ID: 36268
Well Name: OVV HZ SUNRISE K04-14-080-17
Location: DLS: K04-14-080-17

Permit: 100105158
Well ID: 36269
Well Name: OVV HZ SUNRISE L04-14-080-17
Location: DLS: L04-14-080-17

Permit: 100105158
Well ID: 36270
Well Name: OVV HZ SUNRISE D03-14-080-17
Location: DLS: D03-14-080-17

Permit: 100105158
Well ID: 36271
Well Name: OVV HZ SUNRISE E03-14-080-17
Location: DLS: E03-14-080-17

Permit: 100105158
Well ID: 36276
Well Name: OVV HZ SUNRISE 03-14-080-17
Location: DLS: 03-14-080-17

Permit: 100105158
Well ID: 36277
Well Name: OVV HZ SUNRISE A03-14-080-17
Location: DLS: A03-14-080-17

Permit: 100105158
Well ID: 36278
Well Name: OVV HZ SUNRISE B03-14-080-17
Location: DLS: B03-14-080-17

Permit: 100105158
Well ID: 36279
Well Name: OVV HZ SUNRISE C03-14-080-17
Location: DLS: C03-14-080-17

Permit: 100080841
Facility ID: 00018153
Facility Name: OVV SUNRISE 04-14-080-17 001
Facility Type: Well Facility
Location: DLS: 04-14-080-17

Permit Holder: Ovintiv Canada ULC



Inspection Number: 2026-1527
Inspection Date: 2026-05-08

Letter ID: L2602186
Letter Date: 2026-05-13

Authorized by BCER