

## Inspection Report

Permit Holder: Pavilion Energy Corp.  
Inspection: 2026-1538  
Inspection Date: 2026-05-12  
Inspection Outcome: Non-Compliance(s) Found

### Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1510HRS.

Access road- Wet in spots. No concerns at the time of inspection.

Lease environment- Vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Well appears active (Last production record Jan 2026). Unknown high pitch whistling coming from connection on wellhead- No alarm on personal monitor. Barricades in place. Signage at lease entrance and on wellhead. Surface casing vent flow test- No Flow detected from glove test. Building entry test- Unable to access meter box due to broken locking clasps on panel (See attached).

Tanks on site- Secondary containment 3/4 full. No concerns at time of inspection.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100000343  
Well ID: 00262  
Well Name: PAVILION STODDART 02-13-086-20  
Location: DLS: 02-13-086-20

---

Authorized by BCER