

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-1539
Inspection Date: 2026-05-14
Inspection Outcome: Inspected

Inspection Comment:

Site 02-09 & 07-09-079-17 was inspected at or about 1330 hours, it was 15 and overcast. The following was included in the inspection:
Access and signage: no concerns
Site: some ruts, clean and dry
Wellheads: Bull plugs, SCV, locks, leaks, -A07-09 needle valve leaking, A02-09 leak and stain - photos attached
Meter/separator buildings: locks, leaks, caps, vents, - Hi/Lo 02-09 hi/lo no locks, header not inspected
Chemical tanks: leaks, grounds, caps, - no concerns
Riser & pig stations: chains, grounds, - no concerns
NOTE: Operator was called and attended the site, fixes were completed while officer was on site. No further concerns were noted.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100074555
Well ID: 27771
Well Name: OVV CRP HZ SUNRISE A02-09-079-17
Location: DLS: A02-09-079-17

Permit: 100074556
Well ID: 27772
Well Name: OVV CRP HZ SUNRISE 07-09-079-17
Location: DLS: 07-09-079-17

Permit: 100078235
Well ID: 29211
Well Name: OVV CRP HZ SUNRISE A07-09-079-17
Location: DLS: A07-09-079-17

Permit: 100078236
Well ID: 29212
Well Name: OVV CRP HZ SUNRISE 02-09-079-17
Location: DLS: 02-09-079-17

Permit: 100079828
Well ID: 29944
Well Name: OVV CRP HZ SUNRISE B02-09-079-17
Location: DLS: B02-09-079-17

Permit: 100079829
Well ID: 29945
Well Name: OVV CRP HZ SUNRISE C02-09-079-17
Location: DLS: C02-09-079-17

Permit: 100112185
Facility ID: 00027289
Facility Name: OVV SUNRISE 07-09-079-17 001
Facility Type: Well Facility
Location: DLS: 07-09-079-17

Permit Holder: Ovintiv Canada ULC

Authorized by BCER