

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-1547
Inspection Date: 2026-05-14
Inspection Outcome: Inspected

Inspection Comment:

Site 01-34-078-17 was inspected at or about 1400 hours, it was 10 & overcast/showers. The following was included in the inspection:
Access and signage: Gated, No concerns
Site: clean and dry
Wellheads: Bull plugs, SCV, locks, leaks, - audible leak at tubing off annulus, well 01-34 photo, operator attend to the site and was observed until fix was completed
Meter/separator buildings: locks, leaks, caps, vents, - no concerns
Chemical tanks: leaks, grounds, caps, - no concerns

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100068721
Well ID: 25453
Well Name: OVV HZ SUNRISE 01-34-078-17
Location: DLS: 01-34-078-17

Permit: 100072064
Well ID: 26671
Well Name: OVV HZ SUNRISE A01-34-078-17
Location: DLS: A01-34-078-17

Permit Holder: Ovintiv Canada ULC

Authorized by BCER