

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-1548
Inspection Date: 2026-05-12
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100040691
Well ID: 16936
Well Name: OVV HZ CUTBANK A- 074-B/093-P-08
Location: NTS: A- 074-B/093-P-08

Permit: 100043032
Well ID: 17918
Well Name: OVV ECOG HZ CUTBANK B-A073-B/093-P-08
Location: NTS: B-A073-B/093-P-08

Permit: 100043462
Well ID: 17913
Well Name: OVV HZ CUTBANK B- 073-B/093-P-08
Location: NTS: B- 073-B/093-P-08

Permit: 100043678
Well ID: 18240
Well Name: OVV ECOG HZ CUTBANK C- 063-B/093-P-08
Location: NTS: C- 063-B/093-P-08

Permit: 100040691
Facility ID: 00020458
Facility Name: OVV DEEPBASIN A-074-B/093-P-08 001
Facility Type: Well Facility
Location: NTS: A- 074-B/093-P-08



Permit: 100043678
Facility ID: 00020810
Facility Name: OVV DEEPBASIN C-063-B/093-P-08 001
Facility Type: Well Facility
Location: NTS: C- 063-B/093-P-08

Authorized by BCER