

## Inspection Report

Permit Holder: Ovintiv Canada ULC  
Inspection: 2026-1552  
Inspection Date: 2026-05-12  
Inspection Outcome: Inspected

### Inspection Comment:

Access road good. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW and pigging station(s) meet current regulations.

Lease access sign is currently laying on the ground and there is a piece of pipe that appears to be garbage and should be removed if it is.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100059495  
Well ID: 22748  
Well Name: OVV ECOG ET AL HZ CUTBANK C- 043-B/093-P-08  
Location: NTS: C- 043-B/093-P-08

Permit: 100059495  
Facility ID: 00022786  
Facility Name: OVV DEEPBASIN C-043-B/093-P-08 001  
Facility Type: Well Facility  
Location: NTS: C- 043-B/093-P-08

---

Authorized by BCER