

## Inspection Report

Permit Holder: Shell Canada Limited  
Inspection: 2026-1555  
Inspection Date: 2026-05-13  
Inspection Outcome: Inspected

### Inspection Comment:

Access and access signage inspected.

Pad clean.

Wellheads and equipmentn fenced.

Inspected wells. Both are suspended and isolated. Signage clear and legible. No SCV flow observed.

Assosiated pipeline well vegetated.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100069403  
Well ID: 25657  
Well Name: SHELL HZ BRASSEY 12-20-077-19  
Location: DLS: 12-20-077-19

Permit: 100069594  
Well ID: 25767  
Well Name: SHELL HZ BRASSEY A12-20-077-19  
Location: DLS: A12-20-077-19

Permit: 100069403  
Facility ID: 00024266  
Facility Name: SHELL HERITAGE 12-20-077-19 001  
Facility Type: Well Facility  
Location: DLS: 12-20-077-19

Permit: 100069594  
Facility ID: 00024324  
Facility Name: SHELL HERITAGE 12-20-077-19 002  
Facility Type: Well Facility  
Location: DLS: 12-20-077-19



Permit: 100119623  
Road Number: 06838  
Segment IDs (Location): 003 (From DLS: 05-33-077-19 To DLS: 13-20-077-19)

---

Authorized by BCER