

Inspection Report

Permit Holder: Shell Canada Limited
Inspection: 2026-1557
Inspection Date: 2026-05-13
Inspection Outcome: Inspected

Inspection Comment:

Access and access signage inspected.

Pad clean.

Inspect well. Signage clear and legible. No SCV flow observed. Meter inspected.

Associated pipeline well vegetated.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100073513
Well ID: 27228
Well Name: SHELL HZ GROUND BIRCH 11-25-077-20
Location: DLS: 11-25-077-20

Permit: 100073513
Facility ID: 00025084
Facility Name: SHELL GROUND BIRCH 11-25-077-20 001
Facility Type: Well Facility
Location: DLS: 11-25-077-20

Permit: 100073513
Road Number: 01704
Segment IDs (Location): 001 (From DLS: 11-25-077-20 To DLS: 10-25-077-20)

Authorized by BCER