

## Inspection Report

Permit Holder: ConocoPhillips Canada Resources Corp.  
Inspection: 2026-1558  
Inspection Date: 2026-05-13  
Inspection Outcome: Inspected

### Inspection Comment:

For Information Only:

Wellhead is disconnected from flowline and wellhead valves are secured.

Onsite: flarestack, lineheater, meter building, chemical tank, associated surface lines.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100052875  
Well ID: 20978  
Well Name: COP FIREWEED A-A075-I/094-A-12  
Location: NTS: A-A075-I/094-A-12

Permit: 100052875  
Facility ID: 00022006  
Facility Name: COP FIREWEED A-075-I/094-A-12 002  
Facility Type: Well Facility  
Location: NTS: A- 075-I/094-A-12

Permit: 100038513  
Pipeline Project ID: 000012131  
Segment IDs (Location): 9 (From NTS: A- 076-I/094-A-12 To NTS: A- 075-I/094-A-12)

Permit: 100038514  
Pipeline Project ID: 000012132  
Segment IDs (Location): 5 (From NTS: B- 094-I/094-A-12 To NTS: A- 076-I/094-A-12)

Permit: 100066274  
Pipeline Project ID: 000021211  
Segment IDs (Location): 1 (From NTS: B- 062-I/094-A-12 To NTS: A- 075-I/094-A-12)



Inspection Number: 2026-1558  
Inspection Date: 2026-05-13

Letter ID: L2602230  
Letter Date: 2026-05-15

Authorized by BCER