

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-1566
Inspection Date: 2026-05-14
Inspection Outcome: Inspected

Inspection Comment:

Inspect access and access signage.

Pad clean.

Wellheads inspected. Barricaded. Signage clear and legible. No SCV flow observed. Meters inspected.

Pig barrel inspected.

Assotiated pipeline well vegetated.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100054502
Well ID: 21114
Well Name: OVV HZ SUNDOWN B- 058-L/093-P-08
Location: NTS: B- 058-L/093-P-08

Permit: 100054809
Well ID: 21402
Well Name: OVV HZ SUNDOWN B-A058-L/093-P-08
Location: NTS: B-A058-L/093-P-08

Permit: 100054502
Facility ID: 00022068
Facility Name: OVV DEEPBASIN B-058-L/093-P-08 001
Facility Type: Well Facility
Location: NTS: B- 058-L/093-P-08

Authorized by BCER